

ASBESTOS REGISTER / INCIDENT REPORT

Attachment B

Address of property:	Name of Competent person:
40 Asbestos Street Hazardville NSW	Neil Wallace, 0419 285443

Date Identified	Type of ACM	Is it Friable or Non Friable?	Specific location(s)	Is this an accessible area	Condition	Recommendation	Control Priority	Reinspect	Photo No.
22/06/16	Bonded sheeting	Non Friable	The mounting board to the electrical meter box	Yes	Intact	N/A Refer to the Management Plan	Low	22/06/21	1
22/06/16	Fibro sheeting	Non Friable	The flat sheet fibro wall cladding to the front gable walls	Yes	Intact	N/A Refer to the Management Plan	Low	22/06/21	2 & 3
22/06/16	Fibro sheeting	Non Friable	The flat sheet fibro wall & ceiling linings to the first bathroom/WC room	Yes	Intact	N/A Refer to the Management Plan	Low	22/06/21	4
22/06/16	Fibro sheeting	Non Friable	The flat sheet fibro wall & ceiling linings to the locker area	Yes	Intact	N/A Refer to the Management Plan	Low	22/06/21	5

THIS SHEET MUST BE READILY AVAILABLE TO PCBU, OCCUPANTS AND CONTRACTORS

ASBESTOS REGISTER / INCIDENT REPORT

Attachment B 1

Address of property: 40 Asbestos Street Hazardville NSW	Name of Competent person: Neil Wallace, 0419 285443
---	---

Date Identified	Type of ACM	Is it Friable or Non Friable?	Specific location(s)	Is this an accessible area	Condition	Recommendation	Control Priority	Reinspect	Photo No.
22/06/16	Fibro sheeting	Non Friable	The flat sheet fibro wall & ceiling linings to the change room	Yes	Intact	N/A Refer to the Management Plan	Low	22/06/21	6
22/06/16	Fibro sheeting	Non Friable	The flat sheet fibro wall & ceiling linings to the laundry	Yes	One wall sheet near the door is cracked	Short term encapsulate with sealant. Replacement is recommended Refer to the Management Plan	Moderate	22/06/17	7 & 8
22/06/16	Fibro sheeting	Non Friable	Fibro packing between piers & floor framing	No	Intact	N/A Refer to the Management Plan	Low	22/06/21	11 & 12

THIS SHEET MUST BE READILY AVAILABLE TO PCBU, OCCUPANTS AND CONTRACTORS



1. Mounting board



2. Cladding



3. Cladding



4. First bathroom



5. Locker area




6. Change room



7. Laundry



8. Broken sheet



THIS SHEET MUST BE READILY AVAILABLE TO PCBU, OCCUPANTS AND CONTRACTORS

SUSPICIOUS MATERIALS REGISTER

Address of property: 40 Asbestos Street Hazardville NSW	Name of Competent person: Neil Wallace, 0419 2854433
---	--

Date Identified	Type of ACM	Is it Friable or Non Friable?	Specific location(s)	Is this an accessible area	Condition	Recommendation	Control Priority	Reinspect	Photo No.
22/06/16	Fibro sheeting	Non Friable	Lining to the hood/awning.	Yes	Intact	<p>Treat as if the material is ACM until the composition can be confirmed.</p> <p>Refer to the Management Plan</p> <p>Probability Unlikely</p>	Low	22/06/17	9
22/06/16	Fibro sheeting	Non Friable	Any materials of a fibro nature that are concealed, over-sheeted, or are buried in the ground.	No	Unknown	<p>Treat as if the materials are ACM until the composition can be confirmed.</p> <p>Refer to the Management Plan</p> <p>Probability Likely if found</p>	Low	N/A	N/A

THIS SHEET MUST BE READILY AVAILABLE TO PCBU, OCCUPANTS AND CONTRACTORS



9. Hood/awning

THIS SHEET MUST BE READILY AVAILABLE TO PCBU, OCCUPANTS AND CONTRACTORS

INCIDENT/CHANGE OF STATUS

40 Asbestos Street Hazardville NSW

<u>DATE</u>	<u>INCIDENT</u>	<u>LOCATION</u>	<u>REPORTED BY</u>	<u>METHOD/ REMOVAL</u>	<u>CONTRACTOR & COMMENT</u>

To be completed after any removal or change of status such as removal, drilling, encapsulating/covering

THIS SHEET MUST BE READILY AVAILABLE TO PCBU, OCCUPANTS AND CONTRACTORS