



CLEARANCE CERTIFICATE - PART B PURSUANT TO THE CODE OF PRACTICE FOR THE SAFE REMOVAL OF ASBESTOS

SECTION A - CLEARANCE INSPECTION DETAILS

Client details

Name of client:	XXX Contracting Pty Ltd
Client contact details:	Mr Good Removal Contractor 0987 654321

Removal work details		
Date removal work carried out:	28 - 30 December 2015	
Site address where removal work is being/was carried out:	70 Hazard Street Asbestosville NSW	
Details of specific asbestos removal work area(s):	External & internal areas of the main dwelling, garage, outbuildings & shed to a residential property	
Name of licensed asbestos removalist:	Mr Good Removal Contractor	
Name and contact details of licensed asbestos removalist supervisor (if difference to removalist):	As above, 0987 654321	

Inspection details		
Date of clearance inspection:	4 January 2016	
Time of clearance inspection:	1.30 pm	



SECTION B – ASBESTOS REMOVAL WORK PAPERWORK

Was a copy of asbestos removal control plan provided:	Yes
Was a copy of WorkCover notification form provided:	Yes
Is the asbestos removal work consistent with the control plan and notification:	Yes

SECTION C – ASBESTOS REMOVAL WORK AREA VISUAL INSPECTION

Did the inspection of the specific area(s) detailed in Section A find any visual evidence of asbestos remaining as a result of the asbestos removal work carried out:	No.
Is/was air monitoring required:	No
Has additional information been attached such as photographs, plans sketched etc:	Yes

CLEARANCE DECLARATION

I declare that:

The asbestos removal work area and the surrounding area(s) are free from any visible asbestos The transit route and waste routes are free from any asbestos

All asbestos in the scope of the removal work has been removed and any known asbestos is intact.

Neil Wallace, (competent person)

Photographs



1



2



3



4



Photographs 1 - 5 Show some areas that were inspected where ACM had been removed from 70 Hazard Street Asbestosville NSW